



L type

超長爪行程動力夾頭

EXTRA LONG JAW STROKE POWER CHUCK

使用說明書


INSTRUCTION MANUAL

Original instructions




重要 Important Notes :


- 請仔細閱讀本說明書，充分瞭解之後再使用本製品。
本說明書請妥善保管，製品使用者變更時，請將此說明書交給新的使用者。
- Before you use the product. Please read this instruction carefully.
Keep the instruction carefully. If the user of the product altered,
please hand the instruction to the new user.



◎序言

為了確保你的安全，在使用你的夾頭之前，請務必詳閱本說明書內所記載之警告事項，並特別注意文中此  圖形符號下之說明。

◎ INTRODUCTION

To ensure safe operation of your chuck, please read this instruction manual and pay particular attention to instructions marked with  including **IMPORTANT** instructions concerning chuck performance.



若未依照此符號底下的說明來操作機械將引起立即的危險，導致重大傷害或死亡。

Indicates an imminently hazardous situation which, if not avoided, could result in death or serious injury.



若未依照此符號底下的說明來操作機械將引起潛在的危險，導致重大傷害或死亡。

Indicates an potentially hazardous situation which, if not avoided, could result in death or serious injury.



若未依照此符號底下的說明來操作機械將引起潛在的危險，導致中輕度的傷害。

Indicates an potentially hazardous situation which, if not avoided, may result in minor or moderate injury.



依照此符號底下的說明事先了解製品的性能，可避免不正確的操作夾頭。

Indicates for chuck performance and avoiding errors of mistake.

目 錄

CONTENTS

1. 注意事項	3	1. For safe operation.....	3
2. 超長爪行程動力夾頭		2. Extra long jaw stroke power chuck	
2.1 超長爪行程動力夾頭規格	9	2.1 Specification of extra long jaw stroke power chuck.....	9
2.2 中空超長爪行程動力夾頭零件表	11	2.2 Parts list of through-hole extra long jaw stroke power chuck.....	11
2.3 中實超長爪行程動力夾頭零件表	12	2.3 Parts list of non-through-hole extra long jaw stroke power chuck.....	12
3. 拉桿的製作	13	3. Manufacture of draw bar.....	13
4. 安裝		4. Mounting	
4.1 中空超長爪行程動力夾頭安裝步驟	15	4.1 Mounting steps of through-hole extra long jaw stroke power chuck.....	15
4.2 中實超長爪行程動力夾頭安裝步驟	16	4.2 Mounting steps of non-through-hole extra long jaw stroke power chuck.....	16
4.3 螺栓鎖緊的順序	18	4.3 Bolt tightening steps.....	18
4.4 連結法蘭的安裝	19	4.4 Mounting of chuck adapter plate.....	19
5. 使用上的注意事項	20	5. Precautions.....	20
6. 軟爪的製造成形	23	6. Forming of soft jaws.....	23
7. 維護與檢查	26	7. Maintenance and inspection.....	26
8. 故障排除	27	8. Trouble and troubleshooting.....	28
9. 裝配概要圖	29	9. Assembly drawing.....	29

追蹤AUTOGRIP 即刻掌握最新訊息!

FOLLOW AUTOGRIP AND STAY UPDATED WITH THE LATEST NEWS!



*2D圖檔(PDF、DWG格式)、3D圖檔(STEP格式) 可以從官網下載。

*You can download the outline drawing (in pdf or dwg format) and 3D step at AUTOGRIP WEB.

注意事項

FOR SAFE OPERATION

請詳閱本說明書，並依循指示說明。
若未依照指示，錯誤的使用而致引起的
損傷或意外事，本公司概不負責。

Please read this manual and following instructions
carefully. We cannot assume responsibility for
damage or accidents caused by misuse, through
noncompliance with the safety instructions.



DANGER
危險




在安裝檢查或潤滑夾頭時，務必關掉所有電源，確保操作者之安全。

SWITCH OFF power before setting, inspecting, lubricating or changing the chuck to ensure operator safety.

易發生身體或衣物捲入等意外事故。

To avoid accident of operator body or clothes drawn into machine.




當主軸迴轉時，切勿操作切換閥。

Never operate the selector valve and the solenoid valve during the spindle rotation.

主爪閉
JAW CLOSED

主爪開
JAW OPEN



將使夾持力喪失，致工作物飛散產生危險。
Causing fly-out of the workpiece.




夾頭之迴轉數，勿超過容許的最高限度。

Don't exceed the recommended speed of the chuck.

迴轉數增加時，離心力相對的增加而降低夾持力，易導致工作物飛散產生危險，故需依切削條件選擇適當的轉數。

Gripping force decreases due to centrifugal force as speed of chuck increases, thereby causing the discharge of workpiece.






WARNING
警告



未關好安全門之前，切勿啟動主軸開關。
Don't start the spindle before closing the machine door.


Close 關緊

避免工件或夾爪因未關門而飛出。
Workpiece or jaw may scatter while door open.



油壓缸出力不可超過夾頭容許之最大入力。
Don't exceed Max. allowable plunger input force.

輸入力
Input force






如油壓缸出力超過夾頭容許最大值，將致使夾頭變形或破裂之危險。
If input force of plunger is exceeded, chuck may be deformed or broken.



某些型式的迴轉缸內建有 " 逆止閥 " 機構，當電源意外中斷時，能防止迴轉缸內部壓力遽降，保持穩固的夾持。
In case of power failure, AUTOGrip's some cylinders are fitted with check valves and pressure relief valves. When power is restored, the solenoid valve resumes its normal function.

停電時喪失夾持力，致使工作物飛散產生危險。
Power outage may cause fly-out of the workpiece.

停電
Power outage



設定工件在正確的夾持位置
Set the workpiece to the correct gripping position.




WARNING

警告




連結螺絲請依照附表所指定之力矩鎖緊。
Secure mounting bolts with specified torque.

螺絲規格 Bolt size	鎖緊力矩 Tightening torque
M5	7.8 N · m (0.8 kgf · m)
M6	12.7 N · m (1.3 kgf · m)
M8	38.2 N · m (3.9 kgf · m)
M10	72.6 N · m (7.4 kgf · m)
M12	106.8 N · m (10.9 kgf · m)
M14	170.6 N · m (17.4 kgf · m)
M16	250.0 N · m (25.5 kgf · m)
M20	402.1 N · m (41.0 kgf · m)
M22	539.4 N · m (55.0 kgf · m)





應確實給油。
Don't miss to lubricate chuck.

給油不足時，會降低夾持力。
Lowering gripping force caused by insufficient lubrication.



軟爪的高度，必須在最大夾持力的限制範圍。
Height of soft jaw must be in restriction range of maximal clamping force.

使用加高軟爪時，需降低油壓力及迴轉數。
Using higher top jaw than standard should reduce input force and rotating speed.



DOWN
需降壓



WARNING

警告




工件加工以內徑夾持時，需將油壓力降低至正常的 50% 以下。

When chucking components internally, reduce the hydraulic pressure by more than 50%.

如未降低油壓力，可能會因夾持力與離心力的雙重作用而使工件或夾頭受損。

If not reduce the hydraulic pressure, it may cause fly-out of the jaw or the workpiece.





DOWN
需降壓



車削長工件物時，必須以尾座頂心或止振套環支撐。

When machining a long workpiece, steady it with a center of tailstock or support collar.




太長而沒有輔助支撐之工件，會有飛散之危險。
Danger by fly-out of workpiece, if it is too long.



不可隨意改造夾頭。

Don't attempt to modify the chuck.

不當改造會損壞夾頭機能而發生危險。
Danger by function damaged of chuck.






CAUTION **注意**



安裝上爪時，三爪之鎖緊位置必須相同，三爪之重量則盡量一致。
When mounting the top jaw on the chuck, the position should be the same, and mass of each jaw is as much as possible.


動平衡差異過大，易造成機台震動，影響加工精度。
Unbalanced mass will cause larger vibration of the machine, thus result in poor accuracy.




操作機器前，請勿喝酒或服用麻醉性藥物。
Never attempt to operate machine after drinking alcohol taking drugs.




NO!



操作機器前，請勿穿戴手套或領帶。
Never attempt to operate machine with gloves and necktie worn.



NO!





CAUTION


注意



拆裝夾頭時，務必使用吊帶或吊環。


Have to using eyebolt or lifting belt, when mounting or dismantle chuck.

吊帶
Lifting belt




車床
Lathe

吊環
Eyebolt



不使用吊帶將釐生危險。
Without lifting belt will cause danger.


車床
Lathe



夾持工件時，請注意不要被夾到手。

When clamping workpiece, make sure your hand not to be hurt.


DANGER !!
危險



不可敲擊夾頭、夾爪或夾持之工件物。

Never hammer chuck, jaws or clamped workpiece.

NO!





衝擊
SHOCK


2. 超長爪行程動力夾頭

2.1 超長爪行程動力夾頭規格

中空型 Through-hole



2L-2



3L-2

Fig.1

註：紅色數據為 2L-A、3L-A 型之寸法 (The dimensions and the specifications of 2L-A、3L-A type are in red data.)

型號		楔心行程	爪行程 (直徑)	夾持直徑 Chuck Dia.		容許油壓缸 推力	最大夾持力	最高迴轉數	I		重量	適用迴轉缸	最大使用 壓力
Model		Plunger stroke	Jaw stroke (Dia.)	最大 Max.	最小 Min.	Max. D.B. pull	Max. Clamping force	Max. speed	Moment of inertia	Weight		Matching cyl.	Max. pressure
		mm	mm	mm	mm	kN (kgf)	kN (kgf)	min ⁻¹ (r.p.m.)	kg·m ²	kg	MPa (kgf/cm ²)		
2L-205	A4	12	18	138	6	10.4(1060)	11.4(1170)	4200	0.018	6.9	7.7	TK-A533	1.5(15)
2L-206	A5	15	24	170	24	15.7(1600)	17.3(1760)	3600	0.063	14.4	15.6	TK-C646	1.8(18)
2L-208	A5	20	32	215	30	22.9(2330)	27.1(2760)	3000	0.173	22	26	TK-A853	1.9(19)
2L-208	A6	20	32	215	30	22.9(2330)	27.1(2760)	3000	0.173	22	24.2	TK-A853	1.9(19)
2L-210	A6	25	37.5	260	53	31.8(3250)	37.3(3800)	2400	0.33	40	45.5	TK-A1075	2.1(21)
2L-210	A8	25	37.5	260	53	31.8(3250)	37.3(3800)	2400	0.33	40	44	TK-A1075	2.1(21)

型號		楔心行程	爪行程 (直徑)	夾持直徑 Chuck Dia.		容許油壓缸 推力	最大夾持力	最高迴轉數	I		重量		適用迴轉缸	最大使用 壓力
Model		Plunger stroke	Jaw stroke (Dia.)	最大 Max.	最小 Min.	Max. D.B. pull	Max. Clamping force	Max. speed	Moment of inertia	Weight		Matching cyl.	Max. pressure	
		mm	mm	mm	mm	kN (kgf)	kN (kgf)	min ⁻¹ (r.p.m.)	kg·m ²	kg	MPa (kgf/cm ²)			
3L-205	A4	12	18	138	6	15.6(1590)	17.2(1750)	4200	0.019	7.2	8	TK-A533	2.3(23)	
3L-206	A5	15	24	170	24	23.5(2400)	26.0(2650)	3600	0.063	14.7	15.9	TK-C646	2.7(27)	
3L-208	A5	20	32	215	30	34.3(3500)	35.0(3570)	3000	0.18	23	25.7	TK-A853	2.8(28)	
3L-208	A6	20	32	215	30	34.3(3500)	35.0(3570)	3000	0.18	23	24.6	TK-A853	2.8(28)	
3L-210	A6	25	37.5	260	53	47.7(4870)	48.0(4895)	2400	0.35	39.5	46.5	TK-A1075	3.1(31)	
3L-210	A8	25	37.5	260	53	47.7(4870)	48.0(4895)	2400	0.35	39.5	45	TK-A1075	3.1(31)	
3L-212	A8	30	45	315	61	64.7(6600)	61.0(6220)	2100	0.827	67.3	70.5	TK-A1291	3.0(30)	
3L-215	A8	35	52	405	52	84.3(8600)	85.0(8665)	1600	2.58	139	152	TK- A1512-35	2.7(27)	
3L-215	All	35	52	405	52	84.3(8600)	85.0(8665)	1600	2.58	139	145	TK- A1512-35	2.7(27)	

單爪中實型 Non-through-hole single-jaw(1L type)




Fig.2

註：紅色數據為 1L-A 型之寸法 (The dimensions and the specifications of 1L-A type are in red data.)

型號		楔心行程	爪行程 (直徑)	夾持直徑 Chucking Dia.		容許油壓缸 推力	最大夾持力	最高迴轉數	I	重量		適用迴轉缸	最大使用壓力
Model		Plunger stroke	Jaw stroke (Dia.)	最大 Max.	最小 Min.	Max. D.B. pull	Max. Clamping force	Max. speed	Moment of inertia	Weight		Matching cyl.	Max. pressure MPa (kgf/cm ²)
		mm	mm	mm	mm	kN (kgf)	kN (kgf)	min ⁻¹ (r.p.m.)	kg•m ²	kg			
1L-06	A5	20	16	168	5	12.3(1250)	27.3(2780)	3800	0.05	12.5	14.3	RK-100	1.7(17.5)
1L-08	A5	25	20	215	7	15.7(1600)	37.2(3800)	3000	0.15	24.2	27.1	RK-125	1.4(14.3)
1L-08	A6	25	20	215	7	15.7(1600)	37.2(3800)	3000	0.15	24.2	25.3	RK-125	1.4(14.3)
1L-10	A6	30	24	254	17	21.6(2200)	48.5(4950)	2400	0.28	38.8	46	RK-150	1.3(13.7)
1L-10	A8	30	24	254	17	21.6(2200)	48.5(4950)	2400	0.28	38.8	44.3	RK-150	1.3(13.7)

2.2. 中空超長爪行程動力夾頭零件表

型式 Model 2L、3L

2.2. Parts list of extra long jaw stroke power chuck




Fig.3

No.	零件名稱	Name of parts	Q'ty	No.	零件名稱	Name of parts	Q'ty
1	本體	Body	1	14	六角孔圓頭螺栓	Hex. socket cap bolt	3 or 4
2	中仁	Wedge plunger	1	15	軟爪	Soft Jaw	2 or 3
3	主爪	Master jaw	2 or 3	16	軟爪連結螺栓	Soft Jaw mounting bolt	4 or 6
4	T形螺帽	T-nut	2 or 3	17	六角孔圓頭螺栓 (選配)	Hex. socket cap bolt(option)	3
5	拉桿連結螺帽	Draw nut	1	18	六角孔半圓頭螺栓	Hex. socket cap bolt	3 or 4
6	螺帽壓環	Retainer	1	19	六角孔固定螺絲	Hex. socket set screw	2 or 3
7	防塵套	Cover	1	20	六角孔固定螺絲	Hex. socket set screw	2 or 3
8	曲柄銷	Crank pin	2 or 3	21	油嘴	Grease nipple	4 or 6
9	曲柄	Crank	2 or 3	22	鋼珠	Steel ball	1
10	中孔塞	Hex.socket set screw	1	23	彈簧	Spring	1
11	連結法蘭 (選配)	Adapter plate(option)	1	24	密封圈	O-ring	1
12	夾頭安全螺栓	Chuck mounting bolt	3 or 4	25	連結扳手 (附件)	Joint handle(accessory)	1
13	六角孔圓頭螺栓	Hex. socket cap bolt	2 or 3	26	吊環螺栓 (10" 以上附件)	Eye bolt (accessory 10" or over)	1

2.3. 中實超長爪行程動力夾頭零件表

2.3. Parts list of non-through-hole extra long jaw stroke power chuck

型式 Model 1L





Fig.4

No.	零件名稱	Name of parts	Q'ty	No.	零件名稱	Name of parts	Q'ty
1	本體	Body	1	14	六角孔圓頭螺栓	Hex. socket cap bolt	1
2	中仁	Wedge plunger	1	15	軟爪	Soft Jaw	1
3	主爪	Master jaw	1	16	軟爪連結螺栓	Jaw mounting bolt	2
4	壓環	Retainer	1	17	六角孔圓頭螺栓 (選配)	Hex. socket cap bolt(option)	3
5	連結管	Draw tube	1	18	六角孔半圓頭螺栓	Hex. socket cap bolt	3
6	防塵套	Cover	1	19	六角孔固定螺絲	Hex. socket set screw	1
7	檔塊	Block lump	1	20	六角孔固定螺絲	Hex. socket set screw	1
8	曲柄銷	Crank pin	1	21	六角孔圓頭螺栓	Hex. socket cap bolt	1
9	曲柄	Crank	1	22	油嘴	Grease nipple	2
10	T形螺帽	T-nut	1	23	鋼珠	Steel ball	1
11	連結法蘭 (選配)	Adapter plate(option)	1	24	彈簧	Spring	1
12	夾頭安全螺栓	Chuck mounting bolt	4	25	連結扳手 (附件)	Joint handle(accessory)	1
13	中仁定位銷	wedge plunger	1	26	吊環螺栓 (10" 以上附件)	Eye bolt (accessory 10" or over)	1

3. 拉桿的製作

中空拉桿製作 Manufacture of Draw Pipe



拉桿詳圖 Detail of Draw Pipe

$$L = A + G2_{max.} + H - G1_{max.} + M2 + 12$$

Fig.5





Fig.6

夾頭型式 Chuck type	迴轉缸型式 Cylinder type	G1 max.	H	M2	G2 max.	M1	H1	O1(f7)	F max.	E min.	L
3L-205 A4	TK-A533	12	17.5	25	15	M38x1.5	25	35 -0.025 -0.050	M40x1.5	3.5	A+45.5+12
3L-206 A5	TK-C646	15	16.5	25	24.5	M55x2	25	50 -0.025 -0.050	M55x2	5	A+51+12
3L-208 A6	TK-A853	20	17	30	30	M60x2	25	55 -0.030 -0.060	M60x2	5	A+57+12
3L-210 A8	TK-A1075	25	21	35	26.5	M85x2	30	80 -0.030 -0.060	M85x2	5	A+57.5+12
3L-212 A8	TK-A1291	30	26	35	33	M100x2	35	95 -0.036 -0.071	M100x2	5	A+64+12
3L-215 A8	TK-A1512-35	30	34	45	45.5	M130x2	40	125 -0.043 -0.083	M130x2	5	A+94.5+12
3L-215 A11	TK-A1512-35	30	34	45	34.5	M130x2	40	125 -0.043 -0.083	M130x2	5	A+83.5+12

註 :2L 型式之拉桿長度基算同 3L 型式

中實拉桿製作 Manufacture of Draw Bar



拉桿詳圖 Detail of Draw Bar

$$L = A - G1_{max.} - G2_{min.} - 4 + C$$

Fig.7




Fig.8

夾頭型式 Chuck type	迴轉缸型式 Cylinder type	B	C	D	G1 max.	G2 min.	K1	K2	L
1L-06 A5	RK-100	30	30	40	45	-8	M20x2.5	M30x1.5	A-11
1L-08 A6	RK-125	35	40	45	50	-11	M24x3	M33x1.5	A-3
1L-10 A8	RK-125	35	40	55	50	-13	M24x3	M45x1.5	A-1

**WARNING
警告**

- 拉桿厚度增加方能有足夠之強度。若拉桿之強度不足會使其斷裂而喪失夾持力，同時工件飛出，產生危險。
- Increasing the thickness of the draw pipe and secure the strength. If the strength of the draw pipe is insufficient, the gripping force of the chuck will lose. It will cause the workpiece fly out and it will be dangerous.

**IMPORTANT
留意事項**

- 螺牙鬆動是造成振動的主要原因。
- 拉桿厚度 E 為最小極限值強度，加工螺牙 F 時最好選用大直徑，使 E 值盡量可能最大。
- 以抗拉強度 380MPa(38kg/mm²) 以上之材料製作拉桿。
- O1、M1 與 F 同心度需在 0.05mm T.I.R 以內。
- Insecure threads will cause the draw pipe to vibrate.
- With the thickness of draw pipe minimized, thread part "E" to the maximum permissible thread dia.
- For pipe strength, use the material of tensile strength 380MPa (38kg/mm²) of or more.
- O1,M1 should be concentric with "Thread F" within 0.05mm T.I.R.

4. 安裝

4.1. 中空超長爪行程動力夾頭安裝步驟

(1) 將拉桿安裝於油壓缸

- 旋入拉桿至油壓缸之活塞桿螺牙內時，儘可能將活塞桿縮回到底。(如果活塞桿處在行程中間位置，鎖緊螺牙時，可能會損壞到活塞之止迴鎖)

(2) 將油壓缸安裝於主軸上 (油壓缸連接板)

- 檢視油壓缸是否偏擺及油壓管路是否正常，設定油壓力於低壓狀態 (0.4~0.5MPa，4~5 kgf/cm²)，移動活塞讓它運動 2~3 次後停置於前端，然後關掉電源。



CAUTION
注意

- 在安裝或拆下夾頭時，需使用吊帶或吊環固定。(10" 以上夾頭附吊環)。
- 當完成上述動作後，切記取下吊環或吊帶。

4. Mounting

4.1. Mounting steps of through-hole extra long jaw power chuck

(1) Connect the draw bar to the cylinder.

- Screw the draw bar into the cylinder piston rod with the rod retracted as far as it will go. (If it is tightened at the intermediate position, the locking pin of the piston may be damaged.)

(2) Mount the cylinder to the spindle (cylinder adapter)

- Check that the run-out of cylinder is minimized before routing the hydraulic piping. Move the piston at low pressure (0.4~0.5MPa, 4~5 kgf/cm²) two or three times and set the piston at the forward end before switching power off.

- When mounting or removing the chuck, lift it with the crane, using an eyebolt or lifting belt. (For a chuck of 10" or over, the eyebolt is attached.)
- Be sure to remove the eyebolt from the chuck after mounting or removing.




Fig.9

4.2. 中實超長爪行程動力夾頭安裝步驟

(1) 將拉桿安裝於油壓缸

- 旋入拉桿至油壓缸之活塞桿螺牙內時，儘可能將活塞桿縮回到底。(如果活塞桿處在行程中間位置，鎖緊螺牙時，可能會損壞到活塞之止迴鎖)

(2) 將油壓缸安裝於主軸上 (油壓缸連接板)

- 檢視油壓缸是否偏擺及油壓管路是否正常，設定油壓力於低壓狀態 (0.4~0.5MPa, 4~5 kgf/cm²)，移動活塞讓它運動 2~3 次後停置於前端，然後關掉電源。

(3) 將夾頭安裝於拉桿

- 將夾頭的軟爪及防塵套取下，使用扳手插入夾頭的中央孔內，旋轉連接管螺絲，使連接管螺絲鎖入拉桿內，則夾頭與拉桿連接一起。
- 當鎖入連接管螺絲於拉桿時，如果不是很平順的鎖入，那必須重新檢查螺牙是否正確及中心是否傾斜等，若強制用力鎖入將可能造成楔心損壞及精度不良。

4.2. Mounting steps of non-through-hole extra long jaw power chuck

(1) Connect the draw bar to the cylinder.

- Screw the draw bar into the cylinder piston rod with the rod retracted as far as it will go. (If it is tightened at the intermediate position, the locking pin of the piston may be damaged.)

(2) Mount the cylinder to the spindle (cylinder adapter)

- Check that the run-out of cylinder is minimized before routing the hydraulic piping. Move the piston at low pressure (0.4~0.5MPa, 4~5 kgf/cm²) two or three times and set the piston at the forward end before switching power off.

(3) Connect the chuck to the draw bar.

- Remove the soft jaw and cover for the chuck to insert the joint handle in to the central hole of the chuck connect the chuck onto the draw bar, turning the draw screw.
- If the connecting of the chuck and draw bar is difficult, chuck the thread. If connected by force. The wedge plunger will be damaged, thus resulting in poor accuracy.




Fig.10



CAUTION
注意

- 在安裝或拆下夾頭時，需使用吊帶或吊環固定。(10" 以上夾頭附吊環)。
- 當完成上述動作後，切記取下吊環或吊帶。
- When mounting or removing the chuck, lift it with the crane, using an eyebolt or lifting belt. (For a chuck of 10" or over, the eyebolt is attached.)
- Be sure to remove the eyebolt from the chuck after mounting or removing.



WARNING
警告

- 鎖緊螺絲時，請依照標準力矩鎖緊，如果鎖緊力矩不足或太大，將造成螺絲斷裂，工作物飛散產生危險。
- 請使用附屬之螺絲。
- Tighten the mounting bolt according to the specified torque. If tightening torque is insufficient or too strong, bolts are broken. Also, the workpiece scatters, thus resulting in danger.
- Use only attached bolt.

螺絲規格 Bolt size	鎖緊力矩 Tightening torque
M6	12.7 N · m (1.3 kgf · m)
M8	38.2 N · m (3.9 kgf · m)
M10	72.6 N · m (7.4 kgf · m)
M12	106.8 N · m (10.9 kgf · m)

螺絲規格 Bolt size	鎖緊力矩 Tightening torque
M14	170.6 N · m (17.4 kgf · m)
M16	250.0 N · m (25.5 kgf · m)
M20	402.1 N · m (41.0 kgf · m)
M22	539.4 N · m (55.0 kgf · m)




WARNING
警告


- 如拉桿鎖入連接之螺帽螺牙不足，將損壞螺牙而使夾持力瞬間喪失造成工件飛散之危險。
- If the draw bar is insufficiently screwed into the draw nut, the thread will be damaged, thus eliminating the gripping force momentarily. It will result in danger due to discharge of workpiece.

4.3. 螺栓鎖緊的順序

- (1) 安裝夾頭至拉桿上
 - 取下夾頭之軟爪及防塵蓋，以 1.2.3 號螺絲鎖入數牙，將連接把手至於夾頭的中央孔上，將連接螺帽鎖入拉桿。
- (2) 安裝夾頭於主軸上
 - 旋轉連接把手至完全結合於主軸接合面。依下列順序鎖上螺絲：1 → 2 → 3 → 4 (如果鎖緊力量不平均將產生偏擺) (鎖緊力矩參考第 17 頁)
- (3) 裝回防塵蓋並檢測夾頭偏擺
 - 使得夾頭外緣極端面偏擺在 0.02mm 內。




1L



2L-2

Fig.11



3L-2

4.3. Bolt tightening steps

- (1) Mount the chuck to the draw bar.
 - Remove the soft jaw and cover of the chuck. Tighten the installation bolts 1.2.3. for several pitches. Insert the joint handle into the central hole of the chuck. Then turn the draw pipe.
- (2) Mount the chuck to the spindle (back plate).
 - Turn the joint handle so that the chuck is thoroughly attached to spindle mounting face.
 - Tighten the installation bolt uniformly: 1 → 2 → 3 → 4 (Uneven installation will be a cause of run-out.) (As for specified torque of the installation bolt, refer to see page 17.)
- (3) Remount the chuck and check run-out of the chuck.
 - Make peripheral run of the chuck to less than 0.02mm.



WARNING
警告

- 連接夾頭之螺絲，請按設定之力矩鎖緊。如鎖緊力矩不足或太強將導致發生意外。
- 以配屬螺絲為使用原則，若特殊情形請採用強度劃分 12.9 以上 (M22 以上 10.0) 並有足夠之長度。
- 使用把手旋轉連接管螺絲來調整楔心在正確位置，如果調整的位置不適當，則夾頭防塵蓋將造成損壞。完成調整動作時，安裝在連接管螺絲後方之止動裝置，必須處於接觸定位點的狀態。



CAUTION
注意

- 使用迴轉缸前請參照說明書。

- Tighten chuck mounting bolts at the specified tightening torque. If the tightening torque is insufficient or too strong, it may cause an accident. Periodically check that bolts are not loosened.
- Use only attached bolts. In an unavoidable case, use bolt with strength code 12.9 (M22 or more: 10.0) or more and sufficient length.
- Turn the draw tube by the handle for adjust the plunger to the correct position. If this adjustment is not suitable, the chuck cover will be damaged. Therefore, as the draw tube holds the click stop equipment, finish the adjustment on the position of the contact.

- For the cylinder, refer to the instruction manual.

4.4. 連結法蘭的安裝

- 連接板外徑之偏擺須在下表所示 D 值範圍內，而連接板端面之偏擺須在下表所示 E 值範圍內。
- 夾頭外徑之偏擺須在下表所示 F 值範圍內，而夾頭端面之偏擺須在下表所示 G 值範圍內。
- Fig.12 為 JIS 短錐度主軸圖。

4.4. Mounting of chuck adapter plate

- The outer diameter run-out of the adapter plate should be D-Value or less. The end surface run-out of the adapter plate should be E-Value or less (see table below).
- The outer diameter run-out of the chuck should be F-value or less. The end surface run-out of the chuck should be G-value or less (see table below).
- Fig.12 shows JIS short tapered spindle.




Fig.12

型號 Model	2L-205 3L-205	1L-06 2L-206 3L-206	1L-08 2L-208 3L-208	1L-10 2L-210 3L-210 2L-12	2L-15 3L-215
寸法 Dim					
A (H6)	110	140	170	220	300
B	82.6	104.8	133.4	171.4	235
C	15	15	17	18	22
D	0.005	0.005	0.005	0.005	0.01
E	0.005	0.005	0.005	0.005	0.01
F	0.02	0.02	0.02	0.02	0.04
G	0.02	0.02	0.02	0.02	0.04



CAUTION
注意

- 製作連接板之直徑須依表列 A-0.01。



WARNING
警告

- 連結連接板用之螺絲，應有足夠之強度（直徑、數量、材質）且需有足夠之力矩可鎖緊。（參考第 17 頁）
- 如鎖緊力矩不足或太大，將導致螺絲斷裂而造成夾頭飛散之危險。
- The diameter of the adapter plate should be A-Value -0.01 (see table above).
- Mount the adapter plate with bolts which have sufficient strength (dia., pcs., and material) and tighten it with specified torque. (See page 17)
- If tightening torque is insufficient or too strong, bolts are broken. Also, the chuck discharges thus resulting in danger.


5. 使用上的注意事項

1. 當要換上爪時，必須清理底爪的齒型部分及 T 型塊的接合部分，否則將造成精度上的不準。
2. 依照工件外形及切削情況來設定油壓壓力，如果管狀的工件被高壓夾持將造成變形。
3. 夾持斜面或錐度的鑄品工件時，使用的特殊爪需具有齒狀之夾持面工件物才不會飛散。
4. 夾持偏心工作物時，偏心重量產生的離心力作用在單一爪上，加工時需使用低轉速。
5. 不可使用與主爪排齒不合之上爪，嚙合度不足，將影響夾持力與精度，嚴重者使主爪損壞。
6. 作業開始之前，使用低轉速試做一次，檢查上爪和工作物的位置是否與刀具、刀具座產生干涉。
7. 如果夾持長的工作物時，使用尾座或中心架支撐另一端。(參考第六頁)
8. 長時間停置機器時，夾頭上不可夾持工作物。
9. 當操作不當或機械故障所造成刀具或刀具座撞擊夾頭，立即停機檢查上爪、主爪、T 型塊、連結螺絲及夾持精度等是否正常。
10. 特殊高度上爪使用之油壓壓力需比標準上爪低。
11. 1L 使用前須做動平衡測試，利用其配重孔校正。




WARNING
警告

- 工作物必須夾持於行程的中點位置，或在中點以內，這樣將可達成最好的精度及穩定度，儘量防止用行程的盡端來夾持工作物。設定爪夾位置時必須注意 T 型螺帽不可以突出主爪。(Fig.13 右)
- T 型螺帽突出底爪，不正確使用方法將造成底爪 T 型螺帽的損壞及精度上的不準。(Fig.13 左)



- It is the most desirable that the workpiece is gripped at mid stroke of the master jaws. To grip the workpiece correctly, avoid gripping at stroke end.
- The T Nut must not protrude from the master jaw.(Fig.13 right)
- The use on condition incorrect will cause damage to the master jaw and “ T ” nut as well as inaccuracy.(Fig.13 left)



5. Precautions

1. When changing the top jaw, carefully clean the serration of master jaw and fitting part of T-nut.
2. Set the hydraulic pressure according to the shape of workpiece and cutting conditions. If, for example, a pipe shaped workpiece is gripped with high pressure, it may cause distortion.
3. When gripping inclined or tapered parts such as casting, etc., use special jaws with spikes so that the workpiece will not discharge.
4. Machine the unbalanced workpiece at a low speed because the centrifugal force by the eccentricity mass of work is applied onto the jaw.
5. Do not use the top jaw in which serration pitch differs from the master jaw. If the workpiece is gripped with serration insufficient engaged. The serration is broken. At this time, the jaw or workpiece discharges thus resulting in danger.
6. Before machining. Run with low speed to check that the top jaws locator or workpiece do not interfere with the tool or tool holder.
7. When gripping a long workpiece, use the tailstock or steady rest. (Refer to page.6)
8. When stopping the machine for a long period of time, remove the workpiece from the chuck.
9. If the chuck or workpiece is misused by interfering with the tool or tool rest due to malfunction or tape error. Immediately stop the machine and check the top jaw, T-nuts, cap screws for mounting jaw and etc., and gripping accuracy.
10. In case of using higher jaw then standard top jaws must use lower oil pressure.
11. 1L must be used before the dynamic balance test, through balance weight hole correction.

Fig.13



WARNING 警告

- 如果上爪鎖緊螺絲，其鎖入 T 型螺帽內的螺紋深度太淺，將致使 T 型螺帽破損。反之，螺絲突出 T 型螺帽底部，則即使螺絲已經鎖緊也無法將上爪完全固定，因此上爪鎖緊螺絲的全長應在距離 T 型螺帽底部內 0~1mm 長。(參考 Fig.14)
- 務必使用附屬 T 型螺帽及固定螺絲 (在無法避免的情況下，使用附屬以外的螺帽及螺絲，其強度劃分必須在 12.9 以上 (M22 以上 10.9)，並且特別注意長度是否足夠)。
- 當 T 型螺帽被鬆開時，不能啟動主軸旋轉，否則上爪及 T 型螺帽會飛散，產生危險。
- If the screwing depth for T-nut of the top jaw mounting bolt is shallow, T-nut may be damaged. If the bolt protrudes from the T-nut bottom, the top jaw is not fixed even if the mounting bolt is tightened. Consequently, the overall length of the top jaw mounting bolt should be 0~1mm from the T-nut bottom. (See Fig.14)
- Be sure to use the attached T-nut and mounting bolt. (In an unavoidable case, use the bolt and nut of strength 12.9 (M22 or more, 10.9) or more and sufficient length.)
- Never start the spindle with T-nut still loosened. The top jaw may scatter. It is dangerous.





Fig.14

IMPORTANT 留意事項

- 上爪是經由 T 型塊及連接螺絲安裝於主爪上並可在主爪排齒調整上爪的位置。
- 如果在安裝上爪時，主爪位於開端，T 型塊與防塵蓋的距離少於主爪的行程，那麼 T 型塊將會撞擊防塵蓋，導致防塵蓋損壞。
- The top jaw is mounted on the master jaw with T-nut and mounting bolt. At this time, the mounting position of the top jaw can be changed by a engaged place of serration.
- If the top jaw is mounted with the master jaw opened, the cover is damaged because T-nut interferes with the cover if the distance between T-nut and the cover is less than the master jaw stroke take extreme care when mounting the top jaw.


- T形螺帽前緣不可突出主爪排齒基準位置，如果超出，T形螺帽將會碰撞到防塵蓋，導致防塵蓋損壞。

- If T-nut front edge protrudes from the reference position of master jaw, T-nut will interfere with cover, so that causing the cover damage.



- 斜線區域為可追加加工範圍。

- Shaded area is possible to bore or tap additionally.



- C 為鑽孔或攻牙可允許之深度。

- C is permissible depth of drilling or processing.

型號 Model	寸法 Dim	A	B	C max.
2L-205/3L-205		46	90	15
1L-06/2L-206/3L-206		61	106	20
1L-08/2L-208/3L-208		68	126	20
1L-10/2L-210/3L-210		74	160	20
3L-212		86	180	30
3L-215		115	240	30

動平衡

- 當進行追加加工或用治具時不可產生不對稱。不對稱會造成震動和噪音，使加工精度降低。
- 當加工不對稱大的工件時由於工件的重量形心引起的離心力加在上爪，要充分檢討後以低轉速加工。
- 安裝使用說明書的允許均衡量是以 JIS B 0905-1992 定義的許用均衡 4mm/s 為基準。
- 夾頭的不平衡量的大小規定在表格。(JIS B 0905-1992 相對應的國際標準是 ISO 1940-:1986 和 ISO 8821-:1989)

Balance

- It's not asymmetry when additionally work or use jigs, otherwise able to cause shaking and noise, then reduce the working accuracy.
- The centrifugal force due to centroid of the workpiece is applies to the top jaw when processing asymmetry workpiece, consideration to process with the low speed.
- Tolerance of instruction manual is use balance 4mm/s as the datum with that defines for JIS B 0905-1992.
- Unbalance value of the chuck is stipulate for the form.(JIS B 0905-1992 correspond to international standard is ISO 1940-:1986 and ISO 8821-:1989)

6. 軟爪的製造成形

- 調整軟爪位置可將固定主爪之六角孔圓頭螺絲鬆開使與主爪分離。
- 依據工件大小、尺寸、質料、表面精度及切削條件來選擇合適之軟爪。
- 軟爪製程中油壓壓力必須與實際工作時相同或較低。

IMPORTANT 留意事項



- 盡可能將工件夾持在行程中點。

6. Forming of soft jaws



- Since the soft jaw can be easily separated from the master jaw by loosening hexagon socket head screws, it can be freely adjusted by changing the engaged position on the serration.
- Fit a suitable soft jaw according to the shape, size, material, surface roughness and cutting conditions of the workpiece.
- Adjust the cylinder pressure in forming the soft jaw to the same or less as cutting a workpiece.







- It is desirable to chuck the workpiece in the central part of the stroke.

外徑夾持 External gripping

<p>①</p> 	<p>準備一個表面粗度 $\nabla\nabla\nabla$ 內且無變形內壁厚度的適當圓盤。 注意) 先備妥不同尺寸之圓盤。</p> <p>Prepare the plug for forming. Forming outer dia. Of plug is limited to $\nabla\nabla\nabla$ finishing. Ensures the plug is strong with a suitable wall thickness. Note) It is necessary to prepare different size plugs in advance.</p>
<p>②</p> 	<p>以切換閥將主爪完全打開。 而後計算直徑 D 使持 d 時主爪位於行程中點處。</p> <ul style="list-style-type: none"> Open the master jaw fully by operating the valve. Next, set ØD dimension to grip around the middle of the maximum jaw stroke. <p>$\text{ØD} \doteq \text{Ø0d} + \text{Max Stroke of jaw} / 2$</p>

內徑夾持 Internal gripping






<p>①</p> 	<p>準備一個內徑表面粗度在 $\nabla\nabla\nabla$ 內且不變形具有適當厚度之圓環。</p> <p>Prepare a ring with outer diameter is limited to $\nabla\nabla\nabla$ finishing and with a suitable wall thickness.</p>
<p>②</p> 	<ul style="list-style-type: none"> 以切換閥將主爪關至最小。 而後計算直徑 D 使夾持 d 時主爪位於行程中點處。 Close the master jaw as far as it will go by operating the valve. Next, set ØD dimension to grip around the middle of the maximum jaw stroke. <p>$\text{ØD} \doteq \text{Ø0d} - \text{Max Stroke} / 2$</p>

<p>③</p> 	<p>以切換閥使 ØD 之成型部分夾持圓盤。 必須以夾頭端面支撐以防止傾斜。 注意) 開合夾頭數次，以確定圓盤夾持正確。</p> <p>Grip the plug in ØD by operating the valve.</p> <p>Note) Be sure the plug is correct so that repeat chucking several times.</p>	<p>③</p> 	<p>以切換閥使 ØD 之成型部分夾持圓盤。 必須以夾頭端面支撐以防止傾斜。 注意) 開合夾頭數次，以確定圓盤夾持正確。</p> <p>Grip the ring in ØD part by operating the valve.</p> <p>Note) Be sure the plug is correct so that repeat chucking several times.</p>
<p>④</p> 	<p>成型一個工件夾持部份 Ød 時，需持續夾持圓盤，其尺寸必須相同 (H7) 於工件之夾持直徑，且表面粗度小於 6s。 製程中其壓力必須與實際夾持工件時相同。 注意) 如圓盤產生變形時，須降低壓力或以較厚之圓盤。</p> <p>Form the part Ød for gripping the workpiece with the plug still gripped.</p> <p>Machine the part Ød' to the same diameter(H7) as the workpiece and surface roughness less than 6s.</p> <p>Set the gripping pressure for the jaws to be approximately the same as when the workpiece is gripped.</p> <p>Note) If the plug is distorted, reduce the pressure or alternatively use a stronger plug with additional wall thickness.</p>	<p>④</p> 	<p>成型一個工件夾持部份 Ød 時，需持續夾持圓盤，其尺寸必須相同 (h7) 於工件之夾持直徑，且表面粗度小於 6s。 製程中其壓力必須與實際夾持工件時相同。 注意) 如圓盤產生變形時，須降低壓力或以較厚之圓盤。</p> <p>Form the part Ød for gripping the workpiece with the plug still gripped.</p> <p>Machine the part Ød' to the same diameter(h7) as the workpiece and surface roughness less than 6s.</p> <p>Set the gripping pressure for the jaws to be approximately the same as when the workpiece is gripped.</p> <p>Note) If the plug is distorted, reduce the pressure or alternatively use a stronger plug with additional wall thickness.</p>
<p>⑤</p> 	<p>成型後，夾持工件以檢查夾頭行程。 試切工件而後檢視其加工精度...等。 使用內徑 (A) 及端面 (B) 來夾持。</p> <p>After forming jaws, grip the workpiece to check the jaw stroke.</p> <p>Perform trial cutting to inspect machining accuracy,etc.</p> <p>Grip the workpiece 2-face fitting of face A and face B. check and face(B).</p>	<p>⑤</p> 	<p>成型後，夾持工件以檢查夾頭行程。 試切工件而後檢視其加工精度...等。 使用外徑 (A) 及端面 (B) 來夾持。</p> <p>After forming jaws, grip the workpiece to check the jaw stroke.</p> <p>Perform trial cutting to inspect machining accuracy, etc.</p> <p>Grip the workpiece 2-face fitting of face A and face B. check and face(B).</p>

**IMPORTANT
留意事項**

高夾持精度時的成型方法（例：外徑夾持情況）
欲達成高夾持精度時，可如圖 1 來成型夾具，
軟爪成型必須與實際加工情況相同。

Method for forming soft jaws when higher accuracy is required (e. g. External gripping)
with jigs used as shown in the following figure, soft jaws can be formed under the same conditions as the machining of the workpiece. jaws will enable higher accuracy to be achieved.

<p>①</p> 	<p>準備好成型的夾具（市售亦可）安裝銷（例 1）或螺絲及螺帽（例 2）於一個圓環狀三等分的金屬板上。使用一個沒有變形及內壁有一定厚度的圓環。</p>	<p>Prepare jigs for forming. (Available also from market) Fit pins (EX.1) or nuts and bolts (EX.2) to the ring shaped plate divided equally into three. Use a strong ring with a suitable wall thickness.</p>
<p>②</p> 	<p>以切換閥將主爪開至最大。</p>	<p>Fully open master jaws by operating the valve.</p>
<p>③</p> 	<p>以切換閥把成型夾具的突出部分插入軟爪的螺絲孔內，而後將其夾持，此時將成型夾具的端面部分與軟爪的前端壓合，如此在夾持時方不致於震動。夾持時，檢查主爪是否位於行程中點附近。 製程中油壓力必須與實際夾持工作物時相同或較小。</p>	<p>Operating the valve, insert projections of jig into the bolt holes of the soft jaw before gripping. At this time, enforce the jig to the jaw, ensuring closed fit. Check that the work is gripped nearby center of correct stroke. Set the hydraulic pressure to form jigs to the same or less pressure when the workpiece is machined.</p>
<p>④</p> 	<p>保持成型夾具被夾持的情況，成型工作物的夾具部分 $\varnothing d'$，加工 $\varnothing d'$ 時尺寸必須與工件夾持部分的直徑相同 (H7)，而表面精度比 6s 還小。</p>	<p>Form the part $\varnothing d'$ for gripping the workpiece with the plug still gripped. Machine the part $\varnothing d'$ to the same diameter (H7) as the workpiece and surface roughness than 6s.</p>
<p>⑤</p> 	<p>成型後夾持工件以檢視其行程。試切後測試工件精度。使用內徑面 (A) 及端面 (B) 來夾持。</p>	<p>After forming jaws, grip the workpiece to check the jaw stroke. Perform trial cutting to inspect machining accuracy, etc. Grip the workpiece 2-face fitting of face A and face B.</p>

7. 維護及檢查

7. Maintenance and inspection



WARNING 警告

- 長時間定期地潤滑可保持夾頭壽命。錯誤的潤滑將導致夾持力減弱、精度不良、磨損及卡住，故必須潤滑夾頭。
- To maintain the chuck for a long period of time, it is necessary to lubricate the chuck on a regular basis. Inadequate lubrication causes malfunction at low hydraulic pressure, reduces gripping force and affects gripping accuracy, and causes wear and seizure. Consequently, securely lubricate the chuck.

潤滑的處所	潤滑油種類	潤滑週期
使用潤滑油槍將潤滑油注入每一個主爪周圍的油嘴。	二硫化鉬潤滑油	每日一次，但如果夾頭在高速旋轉或大量的水性切削液於加工中使用時，需要更多的潤滑，請依照不同的情況來決定。

Section to be lubricated	Grease useds	Lubrication cycle
Apply grease from the grease nipple at the periphery end of each master jaw with a grease gun.	Moly Kote EP Grease (DOW CORNING CO.,LTD)	Once a day. However, when the chuck is operated at high speed rotation or a large amount of water soluble cutting oil is used, more of lubricated is needed according to service conditions.

- 加工完後務必以風槍或類似的工具清潔夾頭本體及滑道面。
- 避免因生鏽而降低夾持力，需使用防銹之切銷油。
- After machining, clean the chuck body and slideway with air gun, etc.
- Use rust prevention coolant oil so that rust does not reduce gripping force.



CAUTION 注意

- 每六個月 (或每 10 萬次) 取下夾頭做一次徹底之清潔 (切削鑄鐵則每二個月至少一次)。
檢查零件有無損壞或磨損，如嚴重時立即更換新品。
- 組裝前須充份潤滑。
- Disassemble and clean the chuck at least once per 6 months or every 100,000th used (once every two months for the casting). See if parts are worn or cracked and replace it if required.
- Lubricated the chuck before reassembling.

8. 故障排除

- 如夾頭故障，請停下來檢查，依下列情況來處理。

不正常情況	可能原因	對策
夾頭不能動作	夾頭的零件損壞。	分解夾頭及更換。
	滑動部份被卡住。	分解夾頭及取出被卡住的部份，以油石修整之或更換。
	迴轉油壓缸停止運作。	檢視油壓系統，如減壓閥、洩壓閥…等。
主爪的全行程不足	內部積存了太多的雜屑。	分解後清理。
	拉桿鬆脫。	重新鎖緊拉桿。
工作物有滑動的情況	主爪的夾持行程不足。	重新夾持工件使得主爪的位置於行程的中點。
	夾頭的夾持力不足。	檢視所設定的油壓壓力是否到達。
	上爪的形成直徑與工件的直徑不同。	使用正確的成形方法重做一次。
	切削力量太大。	重新計算一次切削力量而確認是否合乎此夾頭的規格。
	主爪滑道的潤滑油不足。	依據潤滑過程重新潤滑各部而後在沒有工件下操作夾頭數次。
	迴轉速度過高。	降低迴轉數到標準內，以減少離心力的影響。
精度不良	夾頭之外徑偏擺過大。	校正外徑或端面的偏擺及鎖緊螺絲。
	主爪與上爪間有外在因素干預，如灰塵…。	取下夾爪並且完全清理。
	上爪固定螺絲沒有鎖緊。	以適當力矩鎖緊。
	夾持力過大，使工件變形。	降低夾持力到適當程度，使得機器可以夾緊工作物但不致變形。
	上爪高度太高，使上爪或固定螺絲變形。	降低上爪至標準高度。(選用一個標準的尺寸)
	在成形上爪的過程不當或不完善。	確定成形圈是否對稱，與平行在夾頭之端面。 檢查成形圈的外形是否因夾持力過大而導致變形。 例外，檢查在成形時油壓壓力及成形面的表面粗度。

備註：

簡單的故障請自行處理，如無法自行處理或特殊狀況時，可通知您的經銷商或寄回本公司處理。

8. Troubleshooting

- If the chuck malfunctions, stop the lathe and try the following countermeasures.

Problem	Possible Reasons	Countermeasures
Chuck will not work	Chuck part is damaged.	Disassemble and replace part.
	Slidway seizes.	Disassemble and repair damaged part with oil stone or make change.
	Chuck is not working.	Examine the hydraulic system, pressure reduction valve, over valve.....etc.
Insufficient master jaw total stroke	Too much swarf in chuck.	Disassemble and clean.
	Draw pipe is loose.	Afresh locking Draw pipe.
Workpiece slippage	Insufficient master jaw clamping stroke.	Make arrangement such that when workpiece is chucked the master jaw will be in the stroke center.
	Chucking force is insufficient.	Check that hydraulic pressure adequately set.
	Formed dia of top jaw does not match workpiece dia.	Reform top jaw according to correct method.
	Cutting force is too high.	Calculate cutting force and confirm whether the force matches chuck specifications.
	Insufficient lubrication on master jaws and each slideway.	Lubricate from the grease nipple and chucking operation of jaws several times without workpiece in the chuck.
	Speed is too high.	Reduce speedup to necessary gripping force.
Poor accuracy	Perphery of chuck is run out.	Confirm peripheral and end face run-out and tighten bolts.
	Foreign mater is caught in serrations between master and top jaws, dust...ect.	Remove top jaw and clean serrations thoroughly.
	Top jaw mounting bolts are inadequately tightened.	Tighten bolts to correct torque.
	Workpiece is deformed by too much gripping force.	Reduce gripping force to prevent deformation.
	Top jaw is deformed and top jaw bolts are extended because top jaw is too high.	Reduce the height of the top jaw by replacing with standard size jaw.
	Forming of top jaw is inadequate.	Check that forming plug is parallel to chuck end face and plug is not deformed due to gripping force. Also, check hydraulic pressure while forming, and face roughness.

Remark :

Please contact your local distributor or agent.

If no distributor or agent locally, then contact Autogrip Machinery Co., Ltd.


On receipt of the product, we will inform you immediately of repair chedule.

Please call us if you find any problems.


9. 裝配概要圖

9. Assembly drawing

中空型 Through hole type (2L/3L)



中實型 Non-through hole type (1L)





為精進產品品質，本公司擁有變更之權利，如有變更恕不另行通知。
We reserve the right to modify without prior notice.



佳賀精機股份有限公司
AUTOGRIP MACHINERY CO., LTD.

513006 彰化縣埔心鄉明聖路一段229號
No. 229, Sec. 1, Mingsheng Rd., Puxin Township,
Changhua County 513006, Taiwan

T +886-4-822-8719

F +886-4-823-5719

E sales@autogrip.com.tw

www.autogrip.com.tw



ISO 9001



EBIMK010G
V.2024.10