


- 可用於銑床或加工中心機上，同時加工多個工件。
- 可選擇安裝立式氣缸用保壓閥。
- 可訂製2、3、6工件數的盤面。
- Use for milling machine or machining center to achieve simultaneous processing of multiple workpieces.
- Stationary cylinder lock valve (optional) can be mounted.
- Plate for 2,3,6 stationary chucks is optional.



保留規格修改的權利  
Subject to technical changes

### 外型尺寸 DIMENSIONS

| Model     | A   | B   | C1  | C2  | C3  | C4  | D   | E   | F   | G   |    |     |
|-----------|-----|-----|-----|-----|-----|-----|-----|-----|-----|-----|----|-----|
| MP4-06206 | 460 | 580 | 400 | 320 | 250 | 200 | 544 | 210 | 220 | 120 |    |     |
|           |     |     |     |     |     |     |     |     |     |     |    |     |
| Model     | H   | J   | K   | L   | M   | N   | P   | Q   | R   | S   | T  | U   |
| MP4-06206 | 20  | 45  | 18  | 17  | 20  | 140 | *B  | 33  | 18  | 20  | 20 | 206 |

\*B 對照所裝配夾頭型號之寸法 B。  
The dimension \*B: Please refer to the dimension B of the chuck model assembled.



保留規格修改的權利  
Subject to technical changes

| 最大容許壓力                                  | 操作角度            | 持續口徑      |
|-----------------------------------------|-----------------|-----------|
| Max. pressure MPa(kgf/cm <sup>2</sup> ) | Operating angle | Port size |
| 1.0 (10)                                | 90 °            | Rc1/4     |